# San Antonio Creek Photographs

SA 0001 Hwy 101 & footbridge, SACONFL

SA 0001 Looking upstream from Hwy 101

SA 0001 Asphalt slab on LB

SA 0001 Erosion on LB under oak

SA 0001 Erosion fence & concrete on LB, SAERF01

SA 0001 Failed erosion fence on LB

SA 0001 Concrete embankment on RB, SACCRT01

SA 0001 Concrete grade control structure on LB

SA 0001 Small concrete lip

SA 0002 San Marcos bridge, SASMARC

SA 0003 Upstream from San Marcos bridge

SA 0003 Concrete embankment on LB

SA 0003 Footbridge

SA 0003 Failed erosion fence on LB

SA 0003 Downstream from footbridge, SA03FB

SA 0003 Undercut bank on RB downstream of bridge

SA 0004 Downstream from footbridge after rain

SA 0019 Downstream view

SA 0019 Upstream view

SA 0028 Drainage pipe on RB creating pool

SA 0034 Pool (curves around bend)

SA 0040 Plunge pool & barrier



SA 0041 Cathedral Oaks bridge, SACATHBRG

SA 0041 Underneath Cathedral Oaks Bridge

SA 0044 Downstream view of Cathedral Oaks bridge

SA 0044 Tuckers Grove bridge



SA 0050 Downstream view



SA 0050 Upstream view

SA 0063 Debris Cache

SA 0064 Upstream view of barrier

SA 0067 Road Crossing Barrier

SA 0068 Looking downstream at barrier

SA 0072 Dry trib on RB

SA 0079 Topsoil on surface of water

SA 0084 Pampas grass, SAHU084

SA 0090 Upstream view

SA 0116 Concrete structure (on top of RB)

SA 0134 Upstream view, SAHU134

SA 0144 Plunge pool & scour, SAHU144

SA 0148 Plunge pool



SA 0185 Upstream view of debris basin

SA 0187 Downstream side of debris basin

SA 0188 Pool above debris basin

SA 0200 Upstream view

SA 0210 Downstream view

SA 0210 Upstream view

SA 0222 Downstream view

SA 0222 Upstream view

SA 0257 Downstream view

SA 0258 Erosion under oak on RB



SA 0259 Large boulder on LB

SA 0266 Footbridge, SABHU266

SA 0270 Upstream view

SA 0275 SACASC01, Cascade



SA 0299 Upstream view

SA 0311 Cascade & silt

SA 0326.1 Side channel & erosion

SA 0336 Upstream view

SA 0342 Downstream view



SA 0357 Drainage on RB

SA 0364 Cascade

SA 0366 Cascade (close up)

SA 0368 California newt

SA 0373 Erosion & SWD

SA 0374 Bedrock sheet

SA 0384 Erosion & LWD

| | |
|---|---|
|  | |
| SA 0385 Upstream view | SA 0390 Tributary on RB |

| | |
|---|---|
| | |
| SA 0392 Plunge Pool from Waterfall | SA 0392 Waterfall anadromy limit |

# East Fork San Antonio Creek Photographs

SAEF 0009 Upstream view



SAEF 0013 Dead oaks in unit

SAEF 0016 Runoff from LB



SAEF 0026 Silted-in pool

SAEF 0042 Erosion on RB

SAEF 0046 LWD dam



SAEF 0052 Upstream view

SAEF 0058 Burned area



SAEF 0060 Upstream view

SAEF 0073 Erosion on RB

SAEF 0076 Erosion on RB

SAEF 0091 Upstream view

SAEF 0093.2 Erosion in side channel



SAEF 0094 Cascades

SAEF 0101 Cascade

SAEF 0102 Graded dirt area above LB, US

SAEF 0102 Graded dirt area above LB, DS



SAEF 0119 Burned hillside on LB

SAEF 0120 Burned hillside

SAEF 0126 Arizona crossing

SAEF 0129 Man-made dam

SAEF 0131 Downstream view above dam

SAEF 0132 Burned area on LB

**NO PHOTOGRAPH**